

FIG. 1






FIG. 2



Section of the vessel with internal finned Heat exchanger




FIG. 3c

4/18




FIG. 3d

5/18





FIG. 4

6/18



38




FIG. 5

7/18




FIG. 6

8/18




FIG. 7




FIG. 8

9/18




FIG. 9

10/18




FIG. 10

11/18




FIG. 11




FIG. 12a




FIG. 12b




FIG. 12c

1005627.012502

12/18




FIG. 13

13/18




FIG. 14a




FIG. 14b

14/18




FIG. 15a




FIG. 15b

202310/2299001

15/18




FIG. 15c




FIG. 15d

16/18




FIG. 16a




FIG. 16b

1065637-012502
2022-07-29

17/18




FIG. 17a




FIG. 17b




FIG. 18a




FIG. 18b




FIG. 18c




FIG. 18d




FIG. 18e




FIG. 18f

10055237.0035601

18/18




FIG. 19a




FIG. 19b




FIG. 20

20221026295001